

POKSF
11.3.18.1 V3

SW BATCH DISCHARGE REPORT

Site Information

Company Name

Address

GATX Linnton Terminal
11400 NW St. Helens Rd.
Portland OR 97120

Contact Information

Name

Company Name

Address

Telephone

Facsimile

Peter Murphy
GATX Terminals Corp.
5880 NW St. Helens Rd.
Portland OR 97210
503-220-1250
503-220-1270

Batch Number

SW 2000-002

Discharge Volume

1,787,100

Date Started

01-31-01

Time Started

0830

Date Finished

02-09-01

Time Finished

1130

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to ensure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature:

Peter H. Murphy

Date:

5-13-01

Submit report to:

Industrial Source Control Division
Bureau of Environmental Services
City of Portland
6543 N. Burlington Avenue
Portland, Oregon 97203-5452





Pacific Northern Region - Northwest
Willbridge & Linnton Terminals
5880 N.W. St. Helens Rd., Portland, OR 97210
503-220-1254 PHONE
503-220-1270 FAX

FAX Cover Letter

To: John Holtrop

From: Peter G. Murphy

Re: SW Batch Discharge Report

Pages: 2 (incl. Cover)

John,
I realized that I neglected to send you the
SW BATCH Discharge Report from the hydratest that
we performed in January and discharged in
February. I am sorry that it is so late.

Pete Murphy

TOTAL : 38S PAGES: 2

I realized that I neglected to send you the
5W BATCH Discharge Report from the hydrant that
we performed in January and discharged in
February. I am attaching it to this letter.



GATX TERMINALS CORPORATION
Northwest Operations

5880 N.W. ST. HELENS ROAD
P.O. BOX 83479
PORTLAND, OR 97210/97283
503-220-1240
FAX 503-220-1249

John Holtrop
City of Portland
Environmental Services
6543 N. Burlington Ave.
Portland, OR 97203-5452

1/24/01

Dear John,

TK 55022 has been successfully hydrotested. Enclosed please find a copy of the independent lab Certificate of Analysis. The oil and grease and residual chlorine levels both fall well below the maximum level allowable for discharge. We plan on discharging 5 feet of water at a time. This is only so we can observe our internal floating roof at different levels and is not related to any water quality issues. We will notify you by phone when we intend to start discharging water and will fax the "SW Batch Discharge Report" when we are finished as per our agreement.

If you have any questions, please call me at (503) 220-1254. Thank you for your consideration.

Regards,

A handwritten signature in black ink that reads "Peter G. Murphy".

Peter G. Murphy
Operations Manager
GATX Terminals Corp.

Encl. (1)



CERTIFICATE OF ANALYSIS

PARTIAL REPORT

CLIENT: GATX TERMINALS CORPORATION
5880 N.W. ST. HELENS RD.
PORTLAND, OR 97231

PHONE: (503) 286-1691
FAX: (503) 220-1270

DATE SUBMITTED: 01/15/2001

PROJECT NAME: TANK DISCHARGE WATER ANALYSIS TANK 55022

CI SAMPLE	CLIENTS ID#	DATE	TIME	MATRIX	DESCRIPTION
10089-001		01/15/2001	1425	Water	TANK DISCHARGE WATER SAMPLE
10089-001		01/15/2001	1425	Water	TANK DISCHARGE WATER SAMPLE

REPORT DATE: 01/23/2001 REPORT NUMBER: 10089 PAGE: 1 OF 1

SAMPLE	ANALYSIS	PARAMETER	RESULT	UNIT	DETECTION	ANALYST
TANK DISCHARGE WATER SAMPLE						
10089-001	RESIDUAL CHLORINE 1 EPA 330.4	RESIDUAL CHLORINE	0.6	mg/L	0.1	Dick R. 01/15/2001
	O & G TOTAL (HEM) EPA 1664	TOTAL OIL AND GREASE	ND	mg/L	2	Charles S. 01/23/2001

** Draft Report **

Data in this report may not be complete. This report has not undergone final quality assurance review

TRANSACTION REPORT								P. 01	
								JAN-24-2001 WED 08:52 AM	
DATE	START	RECEIVER	TX TIME	PAGES	TYPE	NOTE	M#	DP	
JAN-24	08:52 AM	95038235559	43"	3	SEND	OK	307		
TOTAL :						43S	PAGES:	3	

P. O Box 83329
 Portland, OR 97283
 Phone (503) 220-1254
 Fax (503) 220-1270

GATX Terminals Corporation Portland, Oregon

To: John Holtrop Fax: _____

From: Peter G. Murphy Date: 1-24-01

Re: Linnton Water Discharge Pages: 3 (incl cover)

CC: _____

☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycl




CITY OF PORTLAND ENVIRONMENTAL SERVICES



Water Pollution Control Laboratory
6543 N. Burlington Ave., Portland, Oregon 97203-5452
(503) 823-5600

December 12, 2000

Peter Murphy
GATX Terminals Corporation
5880 NW St. Helens Rd.
Portland OR 97210



Dear Mr. Murphy:


This letter is in response to the batch discharge request submitted by your facility on December 6, 2000. It is my understanding that the water to be discharged was used to hydro-statically test the above ground storage tank number 55022, and that the water has not been used in any process nor has it been in contact with any product. Due to the apparent lack of pollutants in the water and the large volume, 1,700,000 gallons, it is not appropriate to discharge it to the sanitary sewer. Based on these considerations the City will authorize a batch discharge of hydrostatic-test water to the storm sewer. This is a one-time authorization for this particular discharge only.

This authorization is subject to the following stipulations:

- 1) A sample shall be obtained from the standing water in the tank. The sample shall be analyzed for residual chlorine, and oil & grease. Results of the analysis shall be submitted to the City for review before discharge. The residual chlorine will need to be below 4 mg/l and the oil & grease will need to be below 10 mg/l in order to discharge. It is recommended that you investigate the use of dechlorination chemicals to ensure the chlorine level is below 4 mg/l.
- 2) This office must be notified by phone at the start of the discharge. The contact phone number during business hours is (503) 823-7885. After hours use the spill notification number (503) 823-7180.
- 3) A written account of the date, time, duration, and volume of the discharge needs to be submitted to the City at the conclusion of the discharge.

Please sign a copy of this letter acknowledging your agreement to the above-mentioned terms and return it to this office prior to discharge. If you have any questions concerning the above requirements, please contact the undersigned at (503) 823-7885.

Sincerely yours,



John Holtrop
Bureau of Environmental Services
Industrial Stormwater Section

Agreement to above terms:

Peter G. Murphy, OPS MGR, 12/15/00
Name, Title, Date



CERTIFICATE OF ANALYSIS

CLIENT: GATX - LINNTON TERMINAL
5880 N.W. ST. HELENS RD.
PORTLAND OR 97231

PHONE: (503) 286-1691
FAX: (503) 220-1270

DATE SUBMITTED: 01/15/20

PROJECT NAME: TANK 55022 DISCHARGE WATER ANALYSIS

CI SAMPLE	CLIENTS ID#	DATE	TIME	MATRIX	DESCRIPTION
10089-001		01/15/2001	1425	Water	TANK 55022 DISCHARGE WATER SAMPLE

REPORT DATE: 01/29/2001

REPORT NUMBER: 10089

PAGE: 1 OF 1

SAMPLE	ANALYSIS	PARAMETER	RESULTS	UNITS	DETECTION	ANALYST
					LIMIT	
TANK 55022 DISCHARGE WATER SAMPLE						
10089-001	RESIDUAL CHLORINE 1 EPA 330.4	RESIDUAL CHLORINE	0.6	mg/L	0.1	Dick R 01/15/2001
	O & G TOTAL (HEM) EPA 1664	TOTAL OIL AND GREASE	ND*	mg/L	2	Charles S 01/23/2001

*Note: Value estimate only

REVIEWED BY:

Martin Little - Quality Manager



GATX TERMINALS CORPORATION

5880 N.W. ST. HELENS ROAD
P.O. BOX 83329
PORTLAND, OR 97210/97283
503-220-1260
FAX 503-220-1270

John Holtrop
City of Portland
Environmental Services
6543 N. Burlington Ave.
Portland, OR 97203-5452

12/6/00

Dear John,

Per our earlier discussion, I would like to notify you of our intent to hydrostatically test tank 55022 at our Linnton facility. I expect to use approximately 1.7 million gallons of fresh water to fill the tank. The water will come off a hydrant within our facility and downstream from the main inbound water line.

After the tank is full and we have received your instruction, we will run the necessary tests. We will not drop this water without your permission.

Please fax your response to 503-220-1270. I will be on vacation until December 15th. Please call Dave Denson at 503-220-1250 if you have questions or concerns. Thank you for your consideration.

Regards,

A handwritten signature in black ink that reads "Peter G. Murphy". The signature is stylized with a large, looped "P" and a cursive "Murphy".

Peter G. Murphy
GATX Operations Manager

TRANSACTION REPORT

P. 01

DEC-06-2000 WED 02:57 PM

DATE	START	RECEIVER	TX TIME	PAGES	TYPE	NOTE	M#	DP
DEC-06	02:57 PM	95038235559	31"	2	SEND	OK	316	


TOTAL : 31S PAGES: 2

P. O Box 83329
Portland, OR 97283
Phone (503) 220-1254
Fax (503) 220-1270

GATX Terminals Corporation Portland, Oregon

To: John Holtrop Fax: _____
From: Peter G. Murphy Date: 12/6/00
Re: Hydrotest Pages: 2 (inc/cover)
CC: _____

☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle



CERTIFICATE OF ANALYSIS

CLIENT: GATX - LINNTON TERMINAL
5880 N.W. ST. HELENS RD.
PORTLAND OR 97231

PHONE: (503) 286-1691
FAX: (503) 220-1270

DATE SUBMITTED: 01/15/20

PROJECT NAME: TANK 55022 DISCHARGE WATER ANALYSIS

CI SAMPLE	CLIENTS ID#	DATE	TIME	MATRIX	DESCRIPTION
10089-001		01/15/2001	1425	Water	TANK 55022 DISCHARGE WATER SAMPLE

REPORT DATE: 01/29/2001


REPORT NUMBER: 10089

PAGE: 1 OF 1

SAMPLE	ANALYSIS	PARAMETER	RESULTS	UNITS	DETECTION	ANALYST
					LIMIT	
TANK 55022 DISCHARGE WATER SAMPLE						
10089-001	RESIDUAL CHLORINE 1 EPA 330.4	RESIDUAL CHLORINE	0.6	mg/L	0.1	Dick R 01/15/2001
	O & G TOTAL (HEM) EPA 1664	TOTAL OIL AND GREASE	ND*	mg/L	2	Charles S 01/23/2001

*Note: Value estimate only

REVIEWED BY:


Martin Little - Quality Manager